



# Service Bulletin

SB11-03

June 2011

Page  
1 of 1

127 Walnut St.  
Lindenwood, IL 61049

Phone: 888-825-7323  
[www.swensonproducts.com](http://www.swensonproducts.com)

Fax: 866-310-0300  
E-mail: [warranty@swensonproducts.com](mailto:warranty@swensonproducts.com)

## SUBJECT: Insert Dump Bodies With Cab Shields

### To all concerned:

Swenson has learned that in certain high speed driving conditions, the bed of an empty insert dump body (IDB) may raise while the vehicle is in motion. This could create an unsafe driving condition.

### Corrective Action:

Please perform the following for all IDB units currently sold or in service:

1. **For operator safety, do not transport IDB without first removing cab shield.**
2. **It is your responsibility to inform your customers with these units to remove their IDB units from service until the cab shield is removed.**
3. Once cab shield is removed the IDB can be placed back into service.

Once available, replacement cab shields will be sent directly to distributors who have purchased IDB units. Replacement cab shields will need to be installed on all IDB units previously sold or remaining in your stock. Swenson will reimburse for .5 labor hours to install the replacement cab shield. For more information regarding this service bulletin, please contact Swenson Products at 888-825-7323.

Swenson Products LLC assumes no responsibility for installations not made according to these instructions.

Route To:				
Initial	President/Owner	Sales Manager	Service Manager	Parts Manager