

127 Walnut St.
Lindenwood, IL 61049

Phone: 888-825-7323
www.swensonproducts.com

Fax: 866-310-0300
E-mail: warranty@swensonproducts.com

SUBJECT: Poly tanks with leaking bulkhead fittings

To all concerned:

Swenson has learned that in certain conditions, the brass bulkhead fitting molded directly into the poly spray system tanks may leak. If you encounter a poly tank with the brass bulkhead fittings that are leaking, please follow the corrective action below.

Corrective Action:

Swenson has developed a kit PN 04622-108-00 to replace the brass bulkhead fittings. (1) Repair kit will need to be ordered for each leaking tank. Swenson will reimburse for .5 labor hours per tank. Please contact Swenson at 888-825-7323 to order repair kits or for more information regarding this service bulletin.

When ordering repair kits please have the following information ready:

- Serial number of each affected unit
- Size of the tank (gallons)

Tools required: 1/2" drill, utility knife or deburring tool, tongue & groove pliers

 **DANGER**

Completely drain entire spray system of all liquid. Do not attempt this repair with liquid remaining in any part of the spray system. Refer to chemical manufacturer's MSDS sheet for proper PPE recommendations.

Swenson Products LLC assumes no responsibility for installations not made according to these instructions.

Route To:				
Initial	President/Owner	Sales Manager	Service Manager	Parts Manager